

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

	The state of the s
Company	Dave Shaver
OGM	Karl Houskeeper



Inspection Report

Permit Number:	C0150032
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, September 14, 2011
Start Date/Time:	9/14/2011 9:15:00 AM
End Date/Time:	9/14/2011 12:30:00 PM
Last Inspection:	Thursday, August 18, 2011

Inspector: Karl Houskeeper,

Weather: Cloudy, Temp. 49 Deg. F. InspectionID Report Number: 2866

> Accepted by: jhelfric 9/29/2011

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current /	Acreages
-----------	----------

Total Permitted	6,235.80	
Total Disturbed	27.15	
Phase I		
Phase II		
Phase III		

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State Surface County Loadout Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date Wednesday, Septe



Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Wednesday, September 14, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		~	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Wednesday, September 14, 2011

Page 3 of 3

2. Signs and Markers

The mine identification sign needs to be stabilized. The sign is leaning over and needs to be straightened up. The sign is located at the point of access from the public into the permit area. The sign contains the require information.

The topsoil sign on the topsoil pile (left side looking up canyon) has been placed back on the pole so that it is visible.

4.a Hydrologic Balance: Diversions

The diversion below the coal storage pile area has been cleaned and is fully functional.